Work Order ID 84928 \*84928\* Page 1 May-29-12 2:56:22 PM Item ID: D209-669-043 Accept \*N900040100\* Setup Start **Revision ID:** Item Name: Replacement Skidtube **Start Date:** 29/05/2012 Start Qty: 1.00 Cust Item ID: **Required Date:** 16/07/2012 Req'd Qty: 1.00 **Customer:** Reference: Run Date: 12/05/29 Tooling: Approvals: Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. Work Center ID Description **Run Hours** Code Qty Qty Number \* Stamp **Draw Nbr** Revision Nbr D2906 Rev B 100 0.00 DOCUMENT CONTROL \*100\* 0.00 Memo Memo 0.00 007 per 3c N 12 599

Photocopy D209-669 bluefile & type labels per PPP D205-669-043 Chg 902 per 3c N 12 599 Document Control 110 0.00 Skidtubes \*110\* Skidtubes CF 12.6.18 0.00 Memo Skidtubes - Inspect mat'l D2500-1-190 for damage -Drill pilot holes using drill jig DT8149, DT8711-2 & DT8711-3 (Do not use cutting fluid) -Open holes to 0.500" as per Dwg D2906 without cutting fluid -Deburr and blow out all chips from -Acid etch and Alodine tube per QSI 005 4.1

								· ·	1.45	
Dart Ae	rospace	) Ltd					•		*	<b>L</b>
w/o: &	1978		WO WO	RK ORDER C	HANGES					<del></del>
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
L106-19	20	change Ocz	to QCZ						120713	245
					·					
Part No	: <b>D</b> ?	29-669-013par #:	Fault Categ	ory:	NO	CR: Yes	No DQ	A:	Date:	
•	R	esolution:	Disposition	ı: <u>'</u>	Q/	A: N/C C	losed:		Date: _	
NCR:			WORK ORDE	R NON-CONF	ORMANC	E (NCF	₹)			
-DATE	OTED	Description of NC		Corrective Action	Section B		Verific	ation	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Desc Chief Eng		Sign & Date	🗴   Section		Chief Eng	QC inspect
	1			-	-					3.5

NCR:	•	Y .	ONK ONDE	ER NON-CONFORMANC	E (NCR)			
	0===	Description of NC		Corrective Action Section B		Verification		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	QC inspector
								3.3
	3	N. Carlotte		·				
								*****
		Ya Ya				-		
		44						ţ
		***						
				•				ا بعی
		A CONTRACTOR OF THE PARTY OF TH						*;
				,	1			

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Quality Control

Memo

Page 3 May-29-12 2:56:22 PM D209-669-043 Item ID: Accept \*N900040100\* Setup Start Revision ID: Item Name: Replacement Skidtube **Start Date:** 29/05/2012 Start Otv: 1.00 **Cust Item ID: Required Date:** 16/07/2012 Rea'd Oty: 1.00 **Customer:** Reference: Run **Approvals: Process Plan:** Date: . \* Tooling: Date: Date: \* \* PC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool# Plan Reject Reject Accept Insp. Work Center ID Description Run Hours Code Otv Otv Number Stamp 140 0.00 **BENDING MACHINE - CROSSTUBES** \*140\* ·CNC Bend 1 0.00 Memo CNC Delta 100 Bender 1-Bend as per program COB43FWD & COBRAFT on CNC Bender and Folio FT 2-Cut tubes as per Dwg, D2906 150 0.00 Skidtubes \*150\* Skidtubes Memo CF 12.6.20 Skidtubes -Deburr ends and remove markes from bending - Insert D4202-1 spacer, swage as per QSI002 and trim/ grind flush per QSI002 and dwg. Hold x-bolt with DT9701 Use tube expander 1/2 x17G to start expantion and finish with 1/2 x 180 to x-bolt expantion and finish with 1/2 x 18G to achieve dwg dimention. QC5- Inspect part completeness to step on W/O 160 0.00 \*160\*

W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
·							<u> </u>		
7.	1						<u> </u>		
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No <b>DQ</b>	A:	Date:	.8
	R	esolution:	Disposition	on: <u>'</u>	QA: N/C CI	osed:	<u>.</u>	Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR	)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
		1.							
,									
· ·									
									;

Work Ord  May-29-12 2:5		928		*849	728*							Page 4
ItemID: Revision ID:	D209-669-04			Accept	*N900	040	1100	)*	Setup	Start	*N	IS1*
Start Date: Required Date: Reference:	Replacement S 29/05/2012 16/07/2012	Start Qty: 1.00 Req'd Qty: 1.00	*1 <sup>*</sup>		Cust Item I Customer:	D:				Stop	*N	IS2*
Approvals:	Process Pla		Date:	Tooling:		nte:			Run	Start Stop	*N	R1*
	QC:		Date:	SPC (Y/N):	Da	ite:					*N	R2*
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	t Rej Qty		Reject Number	Insp. Stamp
*170* Skidtubes	*:	Large Fab Memo		0.00		ł			<u> </u>	SP	Ð	12-07-
Skidtubes &		not to hit we	b.Deburr oles for aft & fwd ca	OT8217 Open holes to 19/64", or using DT8215 open holes to ng DT8091-3 , open to .640	o #6" Deburr							

190

QC5- Inspect part completeness to step on W/O

\*190\*

Memo

Quality Control

0.00 5.2107/05

- ai	oopaoc	, E.W								
W/O:			WO	RK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHAI	NGE	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·								
Part No	:	PAR #:	Fault Categ	jory:	NCR:	Yes N	o <b>DQ</b>	A:	Date: _	<u> </u>
	R	esolution:	Disposition	n: <u>'</u>	QA: N	/C Clos	sed:		Date:	
NCR:			WORK ORDE	ER NON-CONFORM	IANCE (	NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng		Sign & Date		cation ion C	Approval Chief Eng	Approval QC Inspector
		1	Sillo. Ling	Office Ling		Dato				
	:					<del>.</del>				
<u> </u>										:
									·	

Work Ord May-29-12 2:50		1928		*849	728*	<del></del>						Page 5
Item ID: Revision ID: Item Name:	D209-669-0			Accept	*N900	)040 ·	100	)*	Setup	Start Stop	*N *N	S1* S2*
Start Date: Required Date: Reference:	29/05/2012 16/07/2012	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item Customer:							17
Approvals:	Process Pla	an:		Tooling: SPC (Y/N):		oate:		]	Run	Start Stop		R1* R2*
Sequence ID/ Work Center II 200 **200* HandFinish Hand Finishing	D	Operation Description Pressure Wash per QSI00 Memo	05 4.3	Set Up/ Run Hours 0.00	Tool ID		Plan Code	Accept Qty	Rejo Qty		Reject Number	Insp. Stamp <u>D. A</u> -5,
210 *210* Powdercoat Powder Coating	841	White Gloss(Ref:4.3.5.1)  Memo START TIM OVEN TEM FINISH TIM	16: 10 - 40 19ERATURE: 30	0.00 0.00 = 2				/χ_	, J			ML -12/07/
220 *220* QC		QC3- Inspect Part Finish  Memo	ιı	0.00				_/ ×	9	<u> </u>	M	11 47 0

Quality Control

Dan Ae	oshace	Liu							~
W/O:			WO	RK ORDER CHANG	SES				
DATE	STEP	PRO	CEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		e e	·						
		k.							
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No <b>DQ</b>	<b>A</b> :	_ Date: _	
	R	esolution:	Disposition	:`	QA: N/C CI	osed:		Date: _	
NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE	OTED	Description of NC			tion B	Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
			-						
:									
									:

Work Orde May-29-12 2:56		928		*849	728*	· <u></u>					Page 6
Revision ID:	D209-669-04 Replacement S			Accept	*N900	040	1100	)*	Setup Sta	I VI	S1*  S2*
Start Date: Required Date: Reference:	29/05/2012 16/07/2012	Start Qty: 1.00 Req'd Qty: 1.00	*1 *1		Cust Item I Customer:	D:		.,		IVI	5/
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):		ate:		J	Run Sta Sto	I <i>Z</i> I	R1* R2*
Sequence ID/ Work Center II 230 *230* HandFinish Hand Finishing	)	Operation Description HandFinishing Memo 1-Install inse	erts & wearnlates as	Set Up/ Run Hours 0.00 0.00 per Dwg. D2906. Use a drop o	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	,
		insert holes l A/R Sika Sikaflex exp 2-Coat D259 per Dwg D2	before installing wearflex-291 Mily Colored	rplates (上りらく フ troleum Jelly and install on D2							

- 5-Wing Walk as per Dwg D2906 and QSI 005 4.4 Batch: M(1) (6)

4-Install D2855 Fwd & Aft Cap as per Dwg D2906 and seal Fwd & Aft Cap with Sikaflex. Clean excess adhesive

A/R Sikaflex-291 //// / 4 G

Sikaflex expire date:

Dail Ac	ospace	Llu							
W/O:			WO	RK ORDER CHANGE	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•					
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
	R	esolution:	Disposition	: '	QA: N/C	Closed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
	OI-LI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		ion C	Chief Eng	QC Inspector
				,					
		. :		,					
l	1		1			1		1	1

<b>Work Orde</b> <i>May-29-12 2:56</i>		928		*84	1928*							Page
Revision ID:	D209-669-04			Accept	*N900	)040	100	)*	Setup	Start Stop	1 1	S1* S2*
Start Date: Required Date: Reference:	29/05/2012 16/07/2012	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item Customer:						I VI	<b>.</b> 7/
Approvals:	Process Pla	n:	Date:	Tooling:	Е	ate:	_	]	Run	Start	*N	R1*
	QC:		Date:	SPC (Y/N):		ate:				Stop	*N	R2*
Sequence ID/ Work Center ID 440	)	Operation Description QC5- Inspect part compl	leteness to step on W/O	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rejo Qty		Reject Number	Insp. Stamp
* <b>?</b> 40*		Мето	·	0.00	Enlose							
uality Control		Inspect Aft ( Foreign obje	Cap, Fwd Step and Wing Vects per QSI 024	Valk of work to Curre	nt Step Inspect for							
50				0.00								
250*		Packaging Memo		0.00						[e]	12/7	123
ackaging			pack for shipping as per P	PPD209-669-043							/ /	

260

QC21- Final Inspection - Work Order Release

0.00

\*260\*

Memo

0.00

Quality Control

ML5 12107/23

	Ториос								
W/O:			WC	ORK ORDER CHANGE	S				
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									·
		·							
	·								
									•
Part No	·	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	<b>A</b> :	Date: _	
	R	esolution:	Dispositio	n: <u>'</u>	QA: N/C C	losed:		Date: _	
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NCI	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		on C	Chief Eng	QC Inspector
		,							
								,	
									,
							····	\$1 241	
		,							

## **Picklist Print**

May-29-12 2:56:26 PM

Work Order ID: 84928

\*84928\*

Parent Item:

D209-669-043

\*D209-669-043\*

Parent Item Name: Replacement Skidtube

**Start Date:** 29/05/2012

**Required Date:** 16/07/2012

Start Qty: 1.00

Required Qty: 1.00

Comments:

new IPP 08.02.13 LL, verified by: DD

IPP Rev:B remove DT # in seq140 DD 10.03.10 Verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4202-1		Manufactured	No		<del>-</del>		Each	81.0000		19			
*D4202-1*				B84	1763				**	19	Œ	12-7-9	<u>L</u>
				Location	!	Loc	<u>Oty</u>	Loc Code					
				LG			5				_		
					77727		5		_		_		
				LG002			76		_		_		
					78806 79810		6				_		
D2500-1-190		Manufactured	No		79010	110	70 Each	91.0000	1 -	1	_		
*D2500-1-1	190*	Manufactured	110			110	Lacii .	91.0000	**	I	CF	12.6	-18
				Location	!	Loc	<u>Qty</u>	Loc Code					
				HALL			91		_		_		
				Á	<b>3000</b>		14 77			0	-		
02926-3		Manufactured	No	`		110	Each	0.0000	1	1			
*D2926-3*				Botto	IQUG				**		_ CF	12.	6-19
D2855		Manufactured	No	<i>\$6</i>	1771	230	Each	21.0000	2	2		•	
<sup>≴</sup> D2855*									**	H	12/0	2109	<u></u>
				Location		<u>Loc</u>	<u>Qty</u>	Loc Code				•	
-				FP002			21						
					65519		2		-		-	-	
					73347 75074		16			y L			

	•	· ·							
W/O:			WO	RK ORDER CHANGES	3			,-	
DATE	STEP	PRO	CEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
				<u> </u>					
Dord No.		DAD #	<b>5</b>						1
Part No		PAR #:							
	R	esolution:						Date: _	······
NCR:		V	VORK ORDE	R NON-CONFORMAN	CE (NCF	<b>(1)</b>			
DATE	STEP	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector
	-								-
				1, 1					

May-29-12 2:56:26 PM

Work Order ID: 84928

\*84928\*

Parent Item:

D209-669-043

\*D209-669-043\*

Parent Item Name: Replacement Skidtube

**Start Date: 29/05/2012** 

**Required Date: 16/07/2012** 

Start Qty: 1.00

\*\*

Required Qty: 1.00

AN3-5A

Purchased

120187

121185

121444

Each

1,090,000

Loc Code

1107/05

\*AN3-5A\* ? x

Location Loc Qty ST350 1090 115371 46 117423 124 118626 31 119355

230

200 500 189

0.0000

AN960JD10L

NAS1149D0332J Purchased

No

No

Each 11015114

\*AN960.ID101 \*⊀ Washer

ALS7-1032-130

Purchased

230

Each

2,136.000 \*\*

\*AI S7-1032-130\* V ALSH-1032-130 / MIZIZG9

Location Loc Qty Loc Code ST280 51 117717 27 118966 22 119775 2 ST282 2085 119530 73 120181 12

2000

Dart Ae	rospace	e Ltd								•
W/O:			W	ORK ORDER CH	ANGES				<del></del>	11/1
DATE	STEP	PROC	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									<u> </u>	
Part No	•	PAR #:	_ Fault Cat	egory:	NCI	R: Yes N	10 <b>DQ</b>	A:	Date: _	<del></del>
	R	esolution:	Dispositi	on: '	QA:	N/C Clo	sed:		Date: _	
NCR:		W	ORK ORE	DER NON-CONFO	RMANCE	(NCR)	)	•		
DATE	CTED	Description of NC		Corrective Action	Section B		Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Date		ion C	Chief Eng	QC inspector
				÷				-	,	
		,			·		-		· · · · · · · · · · · · · · · · · · ·	
•										
						· · · · · · · · · · · · · · · · · · ·				

т	٠		1	•	4				
Р	1	c	ĸ	lis	11:	P	rı	n	t
		·	7	114	, ı			11	ı

Page 3

May-29-12 2:56:26 PM Work Order ID: 84928 \*84928\* Parent Item: D209-669-043 \*D209-669-043\* Parent Item Name: Replacement Skidtube **Required Date:** 16/07/2012 Start Date: 29/05/2012 Start Qty: 1.00 Required Qty: 1.00 AN3C4A Purchased No 230 Each 1,458.000 44 \*AN3C4A\* \*\* 12/07/05 Location Loc Qty Loc Code ST350 1458 120187 57 120521 28 120769 38 121205 1000 V44 121556 335 NAS1149C0332 AN960C10L Purchased No 230 0.0000 Each 11122063 \*AN960C101 \*√ washer D2594-3 Manufactured No 230 Each 2,418.000 \*D2594-3\* \*\* O-Ring, 205 Skidtube Location Loc Oty Loc Code FP001 2418 65518 41 79496 984 79573 50 XI4 79755 1343

Dail Ac	ospace	Liu										
W/O:			WO	RK ORDER CHA	NGES							
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
:						į						
Part No	:	PAR #:	Fault Categ	jory:	NCR	: Yes N	o DQ	A:	Date: _			
	R	esolution:	Disposition	: '	QA:	N/C Clos	sed:		Date: _			
NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Descript Chief Eng	Section B	Sign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspector		
			Office Ling	Oller Elig		Date						
,,,										;		

<b>Picklist Print</b> <i>May-29-12 2:56:26 PM</i>									Page 4
Work Order ID: 84928  Parent Item: D209-669-043  Parent Item Name: Replacement Skin	dtube		928* 09-669-0	)43*			t Date: 29	9/05/2012 00	Required Date: 16/07/2012 Required Qty: 1.00
D2594-1 *D2594-1* Plug, 205 Skidtube	Manufactured	No		230	Each	311.0000	14 **	14 M	nloalos
D3564-9 *D3564-9	Manufactured	F	73401 74442 79495 P-A 73401 78590	<u>Lo</u> 230	98 30 18 50 213 0 213 Each	22.0000	1		12/07/05
Wearshoe		F	76950 P001 67590 69943 82255	<u>Lo</u>	4 4 18 4 1 13	Loc Code			-
<sup>23564-11</sup>	Manufactured	No	3223	230	Each	8.0000 *	1 **	الر	U 12/07/65
Wearshoe		<u>I</u> F	ocation G 77056	<u>Lo</u>	c Oty 4 4	<u>Loc Code</u> B & 3 9 11	·	yι	

May-29-12 2:56:26 PM

FP001

80341

Duit No	oopaoc	Elu									
W/O:			WO	RK ORDER CHANGE	S						
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date: _			
	Re	esolution:	Disposition	•	QA: N/C C	losed:		Date: _	<del></del>		
NCR:	NCR:		WORK ORDE	R NON-CONFORMA	NCE (NC	R)					
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval		
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	Sect	ion C	Chief Eng	QC Inspector		
									-		
					:						
				· · · · · · · · · · · · · · · · · · ·							
	1		1 1			1		1	1		

May-29-12 2:56:26 PM

Work Order ID: 84928 \*84928\* D209-669-043 Parent Item: \*D209-669-043\* Parent Item Name: Replacement Skidtube **Required Date: 16/07/2012 Start Date:** 29/05/2012 Start Qty: 1.00 Required Qty: 1.00 D3564-5 Manufactured 230 Each 13.0000 \*D3564-5\* \*\* 91 12/07/US Wearshoe Location Loc Code Loc Qty FG 2 34806 2 FP001 11 77609 3 82254 8 D3566-1 Manufactured 230 Each 31.0000 \*D3566-1\* \*\* Gasket Location Loc Qty Loc Code FP -22 81619 10 FP002 53 68924 2 80919 3 83898 16 D3566-5 Manufactured No 230 Each 21.0000 \*D3566-5\* Il 12/07/05 \*\* Gasket Location Loc Qty Loc Code FP 12 <u>8</u>2275 12 FP002 80374 3 82274

	oopaoo								
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								:	
				<del></del>					
Part No	•	PAR #:	Fault Cated	jory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
	Re	esolution:	Disposition	<b>:</b>	_ QA: N/C Clo	sed:	·	Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	)			
DATE	OTED	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
į									
	1 1		1		ı	1		1	I

																								10		N	OT	ICE		
																				]	NO	W	0	RJ 32	38		9	ER	M	とナ
																							_		1	2	10	25	12	9
Description		SKIDTUBE ASSEMBLY	SKIDTUBE ASSEMBLY	EXTRUSION	CROSS BOLT SPACER	PLUG	O-RING	AFT CAP	WEB	WEB	WEARSHOE (REPLACES D2577-1)	WEARSHOE (REPLACES D2577-3)	WEARSHOE (REPLACES D2577-5)	WEARSHOE	GASKET	GASKET	GASKET		INSERT				BOLT	BOLT	WASHER	WASHER			TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.	LENGTH OF D2500-1 EXTRUSION BEFORE BENDING = 190 INCHES. INSERT D2926-1-3 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND
Part Number		D2906-041	D2906-043	D2500-1-190	D2579	D2594-1	D2594-3	D2855	D2926-1	D2926-3	D3564-9	D3564-11	D3564-5	D3564-15	D3566-1	D3566-5	D3566-15		ALS7-1032-130	or AKS7-1032-130	or AKS4-1032-130	or ALS4-1032-130	AN3C4A	AN3-5A	AN960C10L	AN960JD10L			PER DART QSI 018 UNI	VEB TO LOCATION SH
ΔTY	-043		×	1	19	14	14	2		1	1	-	1		2	1			44				44	4	44	4		OTES:	SES ARE	F D2500-
αTY	-041	×		1	22	12	12	2	-		l	1	1	1	7	-	Ļ		20				50	4	20	4		GENERAL NOTES:	OLERANC	SERT DZ
											_	_	1	_	_	1_	_	_					_	_	1		-	GEN		ଅଞ୍ଚ ଜନ

**SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY** SUBJECT TO AMENDMENT WITHOUT NOTICE

4

LEGETH OF D2500-1 EXTRUSION BEFORE BENDING = 190 INCHES.

INCREMENT D2926-1-3 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241/291

ADHESIVE PER DART QSI 015 BEFORE BENDING. ENSURE HOLES LINE-UP. BEND AS A SMOOTH RADIUS STARTING WITH A MAXIMUM CENTERLINE RADIUS OF 60 AND ENDING WITH A MINIMUM RADIUS OF 30. A MAXIMUM REDUCTION OF 0.200 IN DIAMETER IS ALLOWABLE IN THE BENT PORTION OF THE TUBE. BEND AS A SMOOTH RADIUS STARTING WITH A MAXIMUM CENTERLINE RADIUS OF 60 AND ENDING WITH A MINIMUM RADIUS OF 30. A MAXIMUM REDUCTION OF 0.200 IN DIAMETER IS ALLOWABLE IN THE BENT PORTION OF THE TUBE.

BEND AS A SMOOTH RADIUS STARTING WITH A MAXIMUM REDUCTION OF 0.200 IN DIAMETER IS ALLOWABLE IN THE BENT PORTION OF THE TUBE.

USE DART DRILL TEMPLATE DT2906-0411 (D2906-043) OR DT2906-0431 (D2906-043) ŝ

TO LOCATE AND DRILL ©0.297 HOLES FOR WEARSHOE INSERTS. INSTALL ALS7-1032-130 PER SECTION C-C AFTER FINISH. INSTALL AN3C4A BOLTS AND AN960C10L WASHERS WITH SIKAFLEX-241/291.
WELDING TO BE DONE PER DART QSI 004. 6


FINISH € **6** 

ACID ETCH, ALODINE PER DART QSI 005 4.1 PRIOR TO INSERTING D2926-1/-3
WEB. POWDER COAT ASSEMBLY WHITE (REF 4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT AS INDICATED PER DART QSI 005 4.4
9) INSERT D2594-1 PLUG CW D2594.3 O-RING IN HOLES MARKED 'P' (BOTH SIDES OF TUBE) AFTER FINISH (12 PLACES).
10) ALL DIMENSIONS ARE IN INCHES.

RELEASED 40.04.04


LTD	IT AEROSPACE	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLED ON THE EXPRESS CONDITION THAT IT IS	8 21	07 08 24	DATE
NTS	SEMBLY	AH-1 (209) SKIDTUBE ASSEMBLY	1	R.	DE APPR
SCALE		TITLE	169	VED	APPROVED
SHEET 1 OF 3		D2906	[F	PR.	MFG. APPR.
REV. B		DRAWING NO.	PH.	G	CHECKED
ADA	ARIO, CAN	HAWKESBURY, ONTARIO, CANADA	CB		DRAWN
LTD	PACE	DART AEROSPACE LTD	cb		DESIGN
DATE	₽	DESCRIPTION	D		REV.
04.06.22	පි		SSUE	NEW ISSUE	4
		PG 3 D7: 38 PLACES WAS 44 PLACES;	7: 38 PLACES	PG 3 D	
		PG 2 C7: REMOVE AFT Ø0.640 HOLE FROM -041; PG 3 C3: CORRECTED -043 CAP P/N:	7: REMOVE AF	PG 2 C	····-
07.08.21	g		PG 1: ADD NOTE 10;	PG 1: /	Δ
		CHANGE WEARPLATE HARDWARE TO SS;	<b>3E WEARPLAT</b>	CHAN	
	TS.	ADD STAINLESS STEEL WEARPLATES AND GASKETS	TAINLESS STE	ADD S	
	_	UPDATE DRAWING FORMAT; RE-ORGANIZE;	TE DRAWING F	- NDDA	

W/O:			V	ORK ORDER CHANG	GES				
DATE	STEP	PRO	CEDURE CH	IANGE	В	,	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Ca	tegory:	_ NCR: Y	es N	o <b>DQA:</b>	Date: _	
	R	esolution:	Disposit	ion:	QA: N/	C Clos	sed:	Date: _	
NCR:			WORK OR	DER NON-CONFORM	ANCE (N	ICR)			
DATE	STEP	Description of NC		, , , , , , , , , , , , , , , , , , ,	tion B		Verification	Approval	Approval
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Oate	Section C	Chief Eng	QC Inspector
							,		
							·		
			·						



Dart Aerospac	e Ltd
---------------	-------

W/O:	•		W	ORK ORDER CHANG	FS		<u></u>		
DATE	STEP	PRO	OCEDURE CH		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	Dispositi	on:	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORI	DER NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC			ion B		cation	Approval	Approval
	J. L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		on C	Chief Eng	QC Inspector
									:
		·							
		•			·				
								1	



Dart	<b>Aeros</b>	space	Ltd
------	--------------	-------	-----

W/O:		- a,	WO	RK ORDER CHANG	iES				•
DATE STÉP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						,			
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQA	\:	Date:	
Resolution:		Disposition:		QA: N/C Closed:			Date:		
NCR:		W	ORK ORDE	R NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	Corrective Action Section			Verification		Approval	Approval
	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Section	Section C Chief Eng		QC Inspector
-	-	÷						e e	•
				· · · · · · · · · · · · · · · · · · ·					,
									·
		•							